



Application Guide

UTILITY BOILERS - OIL/GAS FIRED



Furnace Floor

Normal Service
Plicast Tuff Mix
High Duty Service
Plicast KL 3000
Severe Service
Plicast HyMOR 3100 Special
Plibrico 68S A

Tangent Tube (backup)

Normal Service
Plicast Airlite
High Duty Service
Plicast LWI 20
Severe Service
Plicast Trowl Mix Plus KK
Plisulate 1900 Block

Burner Throats


Normal Service
Plibrico 80 AB
High Duty Service
Plibrico 68S A
Severe Service
Plibrico 85 S Special

Burner Throats

(Water Cooled)
Normal Service
Pligun 3100 Sp
High Duty Service
Pligun HyMOR 8
Severe Service
Plibrico 85 S Special



Application Note



Heat Recovery Steam Generators (HRSG)

Problem—Deterioration of ceramic fiber insulation between steel liner layers in the exhaust gas stack resulting in shell hot spots.

Solution—Insulation injection repair with:

Plistix Injectite 2300
Pligun Verilite (pumped)

Plibrico Company LLC

1010 North Hooker Street
Chicago, Illinois 60622

Tel: 312- 337-9000
Fax: 312- 337-9003

www.plibrico-usa.com

This application guide is intended for general information only. Please consult Plibrico Company or your local Plibrico Representative for specific application assistance and product recommendations.