




Application Guide

SULFUR RECOVERY UNIT




Transition Section

Hot Face
 PliShot HyMOR 3100 Special
 Plibrico HyRATE 60 AB
 Plibrico HyRATE 68 S
 Pligun HyMOR 8

Back Up Insulation
 Pligun LWI 24
 Pligun LWI 26

Boiler Tube Sheet

Plicast 40
 Pligun 40
 Plibrico SR 90



Burner Throat

Plicast HyMOR 3100
 Plicast Super HyMOR 80
 Plibrico 80 AB
 Plibrico 85 S Special
 Pligun HyMOR 8

Combustion Chamber

Hot Face
 PliShot HyMOR 3100 Special
 Plibrico HyRATE 60 AB
 Plibrico HyRATE 68 S
 Pligun HyMOR 8


Back Up Insulation
 Pligun LWI 24
 Pligun LWI 26



Plibrico Company LLC
 1010 North Hooker Street
 Chicago, Illinois 60622

Tel: 312- 337-9000
 Fax: 312- 337-9003

www.plibrico-usa.com



This application guide is intended for general information only. Please consult Plibrico Company or your local Plibrico Representative for specific application assistance and product recommendations.