




# Application Guide

## MUNICIPAL WASTE INCINERATOR



### Typical Mass Burn Incinerator with Recovery Boiler



| Charge Hopper Area    |   |
|-----------------------|---|
| <i>Normal Service</i> | Pligun HyREZIST 2700<br>Pli-Shot HyREZIST 3000      |
| <i>Severe Service</i> | Pligun HyREZIST 3000<br>Pli-Shot HyMOR 3100 Special |

| Ash Hoppers           |  |
|-----------------------|--|
| <i>Normal Service</i> | Pligun Tuff Mix<br>Pli-Shot Tuff Mix           |
| <i>Severe Service</i> | Pligun HyREZIST 3000<br>Pli-Shot HyREZIST 3000 |

| Disposal Chute Area   |                      |
|-----------------------|----------------------|
| <i>Normal Service</i> | Pligun Tuff Mix      |
| <i>Severe Service</i> | Pligun HyREZIST 2700 |

| Studded Water Wall Tubes |   |
|--------------------------|---|
| <i>Normal Service</i>    | Pligun SiC 80<br>Plistix SR 85 (patching) |
| <i>Severe Service</i>    | Plibrico SiC 80<br>Pli-Shot HyMOR SiC 80  |

**Plibrico Company LLC**  
 1010 North Hooker Street  
 Chicago, Illinois 60622

Tel: 312-337-9000  
 Fax: 312-337-9003

[www.plibrico-usa.com](http://www.plibrico-usa.com)

This application guide is intended for general information only. Please consult Plibrico Company or your local Plibrico Representative for specific application assistance and product recommendations.