



Application Guide

REHEAT FURNACES - IN & OUT FURNACE



	Side Walls / Roof / Flue	Insulation
Normal Service	Plibrico Super F AB Plibrico HyRATE Super F AB Pli-Shot HyMOR 3000	Plisulate 1900 Block Pligun LWI 106
Severe Service	Plibrico 60 AB Plibrico HyRATE 60 AB Pli-Shot HyMOR 3100 Special	

	Hearth	Sub-Hearth	Sub-Hearth Insulation
Normal Service	Plicast HyMOR 3000	Plicast 27 C	Plicast LWI 24 Plicast LWI 20
Severe Service	Plicast HyMOR 3100 Special Plicast Si-BOND M		



Plibrico Company LLC

1010 North Hooker Street
Chicago, Illinois 60622

Tel: 312- 337-9000

Fax: 312- 337-9003

www.plibrico-usa.com

This application guide is intended for general information only. Please consult Plibrico Company or your local Plibrico Representative for specific application assistance and product recommendations.